Warrenpoint (William Branson House, Templin House) .2 mile south of State Route 23 (Ric

.2 mile south of State Route 23 (Ridge Road) on small road, approximately 1 mile west of Knauertown

Knauertown Vicinity (Warwick Township)
Chester County
Pennsylvania

HABS, PA, IS-KNATOV, I-

### **PHOTOGRAPHS**

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Heritage Conservation and Recreation Service
Department of the Interior
Washington, D.C. 20243

#### HISTORIC AMERICAN BUILDINGS SURVEY

HABS No. PA-115

### WARRENPOINT

(William Branson House, Templin House)

Location:

.2 mile south of State Route 23 (Ridge Road) on small road, approximately 1 mile west of Knauertown, Knauertown Vicinity (Warwick Township), Chester County, Pennsylvania.

Present Owner:

Mr. Joseph N. Pew, Jr., Ardmore, Pennsylvania.

Present Use:

Unoccupied.

Statement of Significance:

The house is an excellent example of a mid-eighteenth century house with few alterations. The stone work is of interest and much outstanding original interior woodwork remains. The original owner, William Branson, was a leader in early iron and steel production.

# PART I. HISTORICAL INFORMATION

### A. Physical History:

- 1. Original and subsequent owners:
  - 1. Warrant dated Dec. 23, 1356 to Richard Templin, called "Warrenpoint."
  - 2. Conveyed and secured to William Templin by a patent dated Jan. 14, 1802, Patent book 47, p. 81, also see Deed Bk. (Chester Co.) E3, p. 434.
  - 3. Wm. Templin by will dated Feb. 1, 1810 and proved Sept. 14, 1810 (Will Bk. L, <u>p338</u>) left it to son John Templin.
  - 4. John Templin by will dated May 24, 1856 and proved June 16, 1856 (Will Bk. U. p. 474) gave it to Lewis C. Templin.
  - 5. Lewis C. Templin by will proved 1893 (Will Bk. 30, p. 5) left it to wife Hannah B. Templin.
  - 6. Hannah B. Templin by will proved 1895 (Will Bk. 11, p. 467) to J. Wayne Templin.
  - 7. J. Wayne Templin by will proved 1923 to Robert L. & Raymond C. Templin.
  - 8. Robert L. & Raymond C. Templin in 1923 (Deed Bk. Kl6, p.496) to H. Graham Rambo.
  - 9. H. Graham Rambo 1924 (Deed Bk. Olé, p.1) to Truman D. Wade.
  - 10. Truman D. Wade 1924 (Deed Bk. 016, p.3) to Charles B. Montgomery.
  - 11. Charles B. Montgomery 1927 (Deed Bk. M17, p.106) to Joseph Newton Pew, Jr.
- 2. Date of erection: 1756.
- 3. Architect, builder, suppliers: Unknown.

WARRENPOINT
(William Branson House,
Templin House)
HABS No. PA-115 (Page 2)

- 4. Original plans, construction: Unknown, but structure appears to be little changed. The house consisted of a central hall with two rooms on either side plus a kitchen wing to the east.
- 5. Alterations and additions: Few changes are apparent. Most window sash was replaced in the nineteenth century. A three-bay entrance porch was added on the south (front) elevation in the early twentieth century. The house was restored in 1972.
- 6. Important old views:

There is an exterior photograph from circa 1890 in the Chester County Historical Society, West Chester, Pennsylvania.

Eleanor Raymond, <u>Early Domestic Architecture of Pennsylvania</u>, New York, 1931, Plates 39-43 and 134-137.

B. Historical Events Connected with the Structure:

William Branson, the original owner, was a leader in early iron and steel production.

### PART II. ARCHITECTURAL INFORMATION

- A. General Statement:
  - 1. Architectural character: The house is an excellent example of a mid-eighteenth century house with few alterations, interesting stone work, and outstanding original interior woodwork.
  - 2. Condition of fabric: Good.
- B. Description of Exterior:
  - 1. Over-all dimensions: Approximately 44' (five-bay front) x 33' with a kitchen wing 20' x 17' 6" to the east; two-and-a-half stories.
  - 2. Foundations: Stone.
  - 3. Wall construction: Random rubble with contrasting quions.
  - 4. Porches: A three-bay entrance porch was added on the south front in the early twentieth century.
  - 5. Chimneys: There are two massive inside end chimneys on the main block and one on the east end of the kitchen wing.
  - 6. Openings:
    - a. Doorways and doors: Probably all original.

b. Windows and shutters: Most of the window sash was replaced in the nineteenth century. The first floor has shutters, but there were never shutters on the second floor.

### 7. Roof:

- a. Shape, covering: Gable roof with wooden shingles.
- b. Cornice, eaves: Probably original; there are pent eaves across the gable ends.
- c. Dormers: None.

## C. Description of the Interior:

- 1. Floor plans: The first floor has a central hall with two rooms on either side plus a kitchen wing to the east. The second-floor plan is similar, but part of the hall has been converted to a bathroom. The attic is one large room.
- 2. Stairways: Original.
- 3. Flooring: Most of the flooring on the first floor has been replaced, but the original flooring remains in the rest of the house.
- 4. Wall and ceiling finish: Plaster.
- 5. Doorways and doors: Probably original.
- 6. Trim: Mostly original.
- 7. Hardware: Mostly original on the second floor and attic and of the period on the first floor although not original.
- 8. Lighting: Electric.
- 9. Heating: Fireplaces and central heating.

WARRENPOINT
(William Branson House,
Templin House)
HABS No. PA-115 (Page 4)

### D. Site:

- 1. General setting and orientation: The house faces north.
- 2. Enclosures: There is an outdoor cooking area and oven in a stone enclosure at the northeast corner. Only part of the enclosure remained in 1960; it was reconstructed in 1972.
- 3. Outbuildings: General farm buildings.
- 4. Walks, driveways: Long lane from highway.
- 5. Landscaping, gardens: None.

Prepared by Bart Anderson
Curator, Chester County
Historical Society
September 18, 1963
Revised 1979